

From the exterior, Maple Shade Farm house doesn't appear to have a great deal of age. It is two and one half stories tall and is six bays long with three brick chimneys. Beneath the white clapboard, however is a log structure, built in two stages, each being three bays long with center paneled door. It is built on a stone foundation. The windows have 6/6 sash and there is a one story porch on the south facade. On the west gable are four small four-pane casement windows. There are four large-scale dormers on each side of the steeply pitched "A" roof.

The western half of the building has a very fine interior. Originally there was a hall with two rooms to the west, but all partitions have been removed making one large room. The hall has a huge stone fireplace with raised paneling above, and an enclosed stair. The other fireplaces are set diagonally and also have raised paneling above the fireplace. There is a large beaded summer beam, stretching from the two corner fireplaces to the large hall fireplace, with beaded purlins between the outer wall and the summer beam. All flooring exposed from the second floor is beaded at its joints. The first story flooring is oak.

The building is well maintained and is tenanted by resident farmers.

Name Made Shade Farm MHT# CE-212
 Location Cecil Rising Sun
 COUNTY town
on Post Rd ^{1st house} South of Rt 274
 address or road#

First owner of record _____ DATE _____

Present owner Ross Cameron DATE 1968

Address 6 Rd #1 Rising Sun

Parcel or Deed # _____

Original use dwelling

Present use dwelling

Md. Map Coordinates _____

Long. & Lat. reading _____

Style Colonial

Date(s) of construction 18th Century

Architect _____

Builder _____

DESCRIPTION:

2 1/2 Log w/ clapboard
 NUMBER of stories type wall construction

Foundation-basement stone

Wall construction- Log covered w/ clapboard

Water table, string course, other decorative work essential to walls

ND

Chimneys in each gable - brick

Name Maple Shade Farm MHT# CE-212Entrance type & placement 6 panel door b/w 2Windows - same on other half of house -Windows 6/6 - 2 1/2" + 4 pane center, on sw. gableShutters NORoof type A covering

Cornice, eaves

Dormers, cupolas large dormersPorches on S.E. facadeWings, hyphens midw. hitchInterior:
Stairway enclosed - 4 paneled doorDoors 6 panel

Trim

Other notable work exposed summer beam, beaded -beaded parlors - beaded flooring. painted over with
above stage fireplace - 2 corner fireplaces with paneling.
oak flooring

Name Maple Shade Farm MHT# CE-212Physical condition very goodEnvironment farm

References:

MHT Color slide # _____

MHT B & W # _____

Owner contacted tenant

OTHER: _____

Recorder Michael BourneDate Aug 26, 1968

Summary: Maple Shade Farm house is a 2 1/2 story white
clapboard house. It is constructed of log - and is 6 bays long, having
a door between 2

Enclosures: e.g. Map, Historical significance, sketch of floor plan,
and angle of photos, etc.



CE-212

MAPLE SITADE

SOUTH ELEVATION

NX RISING SUN

3/80 PBT

NEG. / MD. HIST TRUST

6



Maple Shade

CE - 212

Interior - East end wall Paneling

Near Farmington

3/80 PBT

NEG - MD. Hist. Trust



~~8425~~

CE-212

~~Maple Shade Farm~~

MAPLE SHADE

FARM

Near ~~Rathen's corner~~ ^{PLLELE GREEN} corner, Cecil County

Hall Paneling

Photographer - Paul Touart, 1979

Neg/MHT



CE-212

Maple Shade Farm

Near College Green, Cecil County

Brick Dairy

Photographer, Paul Touart, 1979

Neg/MHT